RELAYS

AF, AG, AND AJ TYPES (WIRE-SPRING TYPES) REQUIREMENTS (CONDENSED SECTION FOR 040-502-701)

1. REQUIREMENTS (also see Section 020-012-711)

- **1.01** Contact Cover Clearance: Contact cover clears card with cover pushed against stops.
- 1.02 Armature Position: Fig. 1 (A)—Armature hinge spring legs, where secured to armature, bear against outer core legs; relay operated and unoperated.




Fig. 1 - AJ-Type Relay

- 1.03 Balancing Spring Tension: Fig. 1(B)—Card bears against associated surfaces on armature and armature bears against backstop; relay unoperated.
- 1.04 Armature Back Tension: Armature bears against backstop.
 - (a) AF-Type and 12-Position AJ-Type: Min 25 grams (readjust 30 grams; max 60 grams not applicable if nonoperate or release electrical requirements are specified). 70D or 70J gauge.
 - (b) 24-Position AJ-Type: Min 40 grams (readjust 45 grams; max 80 grams not applicable if nonoperate or release electrical requirements are specified). 70D or 70J gauge.
 - (c) AG-Type: Min 15 grams (readjust 20 grams). 70D gauge.

1.05 Contact Make and Break

- (a) Both contacts of movable twin springs make in operated position for make contacts and in unoperated position for break contacts.
- (b) With relay energized against 171A gauge, except where noted, make and break contacts meet following requirements.

SECTION 040-930-701

TEST

- (1) Before Turnover: (Refer to Section 040-502-701 for requirements.)
- (2) After Turnover:

MAKE CONTACTS	NEITHER PAIR OF CONTACTS MAKE ALL RELAYS (INCH)	AT LEAST ONE PAIR OF CONTACTS MAKE ALL RELAYS (INCH)	
Spring combination No. 1 to 199, 500 and up	†# 0.007	0.0015	ļ
Spring combination No. 200 to 399	#0.007	0.0015	İ
Spring combination No. 400 to 499	#0.010	0.0015	
BREAK CONTACTS	AT LEAST ONE PAIR OF CONTACTS DO NOT BREAK ALL RELAYS (INCH)	BOTH PAIRS OF CONTACTS BREAK ALL RELAYS (INCH)	
Spring combination No. 1 to 199, 500 and up	†# 0.007	0.0015	
Spring combination No. 200 to 399	#0.007	0.0015	
Spring combination No. 400 to 499	#0.010	0.0015	

[#] Gauge inserted between armature and backstop.

READJUST

MAKE CONTACTS	NEITHER PAIR OF CONTACTS MAKE TYPE RELAY AF AG & AJ (INCH)	AT LEAST ONE PAIR OF CONTACTS MAKE TYPE RELAY AF AG & AJ (INCH)
M (Make)	$0.012 \qquad 0.0145$	$0.0045 \qquad 0.005$
EM (Early Make)	0.0215 0.0255	0.0135 0.016
PM (Preliminary Make)	0.031 0.0365	0.023 0.027
BREAK CONTACTS	AT LEAST ONE PAIR OF CONTACTS DO NOT BREAK TYPE RELAY AF (INCH)	BOTH PAIRS OF CONTACTS BREAK TYPE RELAY AF AG & AJ (INCH)
B (Break)	‡0.012 ‡0.0145	$0.0045 \qquad 0.005$
EB (Early Break)	0.0215 0.0255	$0.0135 \qquad 0.016$
PB (Preliminary Break)	0.031 0.0365	0.023 0.027

[‡] Relays having spring combination No. 1 to 199 and 500 and up with 7 or more pairs of movable twin springs also meet specified condition with 0.007-inch gauge inserted between armature and backstop.

[†] For relays having six or less pairs of movable twin springs, requirement is met with 0.0045-inch gauge inserted between armature and backstop.

1.06 Contact Sequence

TEST

- (a) *EMB Position*: EM contacts make before B contacts break.
- (b) EBM Position: EB contacts break before M contacts make.
- (c) *PMEB Position*: PM contacts make before EB contacts break.
- (d) *PBEM Position*: PB contacts break before EM contacts make.
- (e) EM, EB, PM, and PB Position: Check sequence if note on circuit requirement table so specifies.

Readjust: Covered by readjust requirment 1.05.

1.07 Buffer Spring Position

(a) With relay energized against 171A gauge, buffer spring meets conditions covered below.

	TYPE RELAY	NO MOVEMENT (INCH)	PERCEPTIBLE MOVEMENT (INCH)
*Test (After Turnover)	All Relays	_	0.0015
Readjust	AF AG & AJ	0.007 0.0085	0.003 0.0035

- *For before turnover requirement, refer to Section 040-502-701.
 - (b) Buffer Spring Positioned by Core Plate:
 Portion of spring between positioning lugs
 rests against core plate; relay operated and
 unoperated.
 - (c) Buffer spring not used; card should not touch spring operating lug; relay operated.
- 1.08 Buffer Spring Tension: Min 20 grams (readjust 25 grams). 70D gauge.

SECTION 040-930-701

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS

CONTACT POSITIONS			e ⁱ	SPRING CO	OMBINATION	N FIGURE N	JMBERS			
	1	2	3	4	5	6	7	8	9	10
12					M	M	M	M	_	_
11	_	_		_		M	M	M	_	
10	_		M	M	M	M	M	\mathbf{M}	_	_
9	_			_	_	M	M	M	_	
8		M	M	М	M	M	M	M	_	_
7	_	_	_	_		_	_	M	В	В
6	M	M	M	M	M	M	M	M	M	M
5	_			_			M	M		В
4			M	M	M	M	M	M		
3	_			_	_	M	M	M	_	-
2	(*)	_	_	M	M	M	M	M	-	_
1	***					M	M			
	11	12	13	14	15	16	17	18	19	20
12	_	M	M	M	M	M		_	M	M
11		_	_	M	M	M				M
10	M	M	M	M	M	M		M	BM	M
9				<u></u>	M	M				
8	M	M	\mathbf{M}	M	M	M	M	BM	BM	BM
7	В	В	В	В	В	В	_	_	_	_
6	M	M	M	M	M	M	BM	BM	$\mathbf{B}\mathbf{M}$	$\mathbf{B}\mathbf{M}$
5			В			В			_	
4	M	M	M	M	M	M		M	BM	M
3		· —		M	M	M	_	_		M
2	M	M	M	M	M	M	_	_	M	M
1				M	M	M			M	<u>M</u>
	21	22	23	24	25	26	27	28	29	30
12	M	_	-		M	M	M	M	M	M
11	М .	_	В		_	M	_	В	M	
10	M			BM	BM	$\mathbf{B}\mathbf{M}$	M	BM	M	M
9	M		В	В		M		В		
8	\mathbf{BM}	$\mathbf{B}\mathbf{M}$	_	BM	$\mathbf{B}\mathbf{M}$	BM	BM	BM	M	M
7	M	_	В	В	В	В	В	В	В	В
6	BM	BM		BM	\mathbf{BM}	BM	BM	BM	BM	BM
5	M		В	В	В	M		В	В	В
4	BM		_	BM	BM	BM	M	BM	M	M
3	M	_	В	В	_	M		В		
2	M	_		M	M	M	M	M	M	M
1	M			_		M		В	M	
M. Molto										

M — Make

B - Break

See Reqt 2.11

BM— Break Make — See Reqt 2.11 and 2.12

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING C	OMBINATIO	N FIGURE N	UMBERS		e se	
	31	32	33	34	35	36	37	38	39	40
12	BM	_		BM	M	_	_	_	<u></u>	В
11	$\mathbf{M}_{\mathbf{x}}$	_	_	M	\mathbf{M}	_	_		_	В
10	BM	\mathbf{M}	M	\mathbf{BM}	M	M		_	-4	M
9		_	В	M	В	В	_	-		В
8	BM	BM	M	BM	M	M	M	M	M	M .
7	В	В	В	M	В	В	В	В	В	В
6	BM	$\mathbf{B}\mathbf{M}$	M	BM	M	M	M	\mathbf{M}	\mathbf{M}	M
5		-	В	M	В	В			В	В
4	BM	M	M	BM	\mathbf{M}	M	_	M	M	M
3	M	_	В	M	В	-	_		0 —	В
2	BM		· —	\mathbf{BM}	M	\mathbf{M}	_	_		\mathbf{M}
1	M			M	M				: -	В
	41	42	43	44	45	46	47	48	49	50
12		\mathbf{M}	_	_	_	_		M	M	_
11	_	В		_	_	_		M	M	_
10		\mathbf{M}	_	_	_	_	*******	\mathbf{M}	\mathbf{BM}	
9		В	В	_	В	_			_	_
8	M	BM	M	M	M	M		M	BM	BM
7	В	В	В	В	В	-	В	В	_	-
6	M	BM	M	BM	\mathbf{M}	M	_	M	BM	\mathbf{BM}
5	В	В	В		В					
4	_	\mathbf{M}		M	M	M	_	M	BM	BM
3	_	$\mathbf{B}^{'}$	В	_	_		_			
2		M		_	_	_	_	M	\mathbf{M}	
1		В						M	M	
	51	52	53	54	55	56	57	58	59	60
12	M	· ()	_	_		В	_	В	BM	_
11	M			_	_	_	\mathbf{BM}	_	В	BM
10	\mathbf{M}	В		\mathbf{M}	В	В	M	M	BM	
9	\mathbf{B}_{a}	_	_	_	_	_	BM	_	В	BM
8	M			BM	M	M		В	BM	
7	В			_	_	_	$\mathbf{B}\mathbf{M}$	_	В	BM
6	BM	\mathbf{M}	В	BM	\mathbf{BM}	BM	В		$\mathbf{B}\mathbf{M}$	BM
5	В	_	_		_		$\mathbf{B}\mathbf{M}$	_	В	BM
4	M		_	M	M	M	M	_	BM	
3	_			_	_	_	$\mathbf{B}\mathbf{M}$	_	В	$\mathbf{B}\mathbf{M}$
2	M		. —	В	-	В	M	BM	BM	_
1	M		_		_	_	BM		В	BM

M-Make

B-Break

See Reqt 2.11.

BM — Break Make — See Reqt 2.11 and 2.12.

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING CO	MBINATION	I FIGURE NUN	MBERS		1	
	61	62	63	64	65	66	67	68	69	70
12 11 10 9	M M M M	M M BM	M M BM M	BM BM BM BM	M — M —	M M 	M — M —	M — M B	— В	BM BM BM
8 7 6 5	BM M BM M	BM - BM -	BM M BM M	BM BM BM BM	M — BM	M B M	B - B -	M B M B	BM — BM —	BM BM
4 3 2 1	M M M M	BM M M M	BM M M M	BM BM BM BM	M — M —	M M M	M — M —	M — M —	BM _ _ _	BM — BM BM
12 11 10 9	71 — — M	72 — — M	73 M — M —	74 — — —	75 B 	76 — — M —	BM BM BM M			***************************************
8 7 6 5	M B 	M B BM B	M B BM	BM - BM -		BM B BM B	BM M BM M			
4 3 2 1	M M —	M M 	M M M	M 	— М М	M — M —	BM M BM BM	···		
12 11 10 9	200 — — M —	201	202 	203 — — EBM —	204 M — M —	205 EMB M EBM	206 EM M M	207	208 EMB — EBM —	209 — — — —
8 7 6 5	EBM B EMB B	EBM — EBM —	EBM B EMB	EBM EBM	EBM B EBM —	EBM — EMB —	EBM — EMB —	EBM EMB 	EBM — EMB	EBM
4 3 2 1	EBM — M —		M 	EBM — — —	EBM — M M	EBM — EBM M	EBM M M M	EBM - - -	EBM — EBM —	
M — Make B — Break		See Re	eqt 2.11		EBM -	Break Make Early Break Early Make	k Make		See Reand 2.	eqt 2.11 12.

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING CO	MBINATION	FIGURE NUN	1BERS			
	210	211	212	213	214	215	216	217	218	219
12	M	·	EM	EM	EM	EM	_	EBM		EMB
11		_	M	_	_	_	_			M
10	M	_	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	M	M	_	EBM	M	M
9			_	В		_		_	_	BM
8	EBM	EBM	EBM	EBM	EBM	EBM	M	EBM	EBM	M
7		_	В	В	В	В		_	В	BM
6	$\mathbf{E}\mathbf{B}\mathbf{M}$	$\mathbf{E}\mathbf{M}\mathbf{B}$	EMB	EMB	EMB	EMB	EMB	\mathbf{EBM}	\mathbf{EBM}	EMB
5		-		В		В	_			BM
4	M		$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM	M	M	M	EBM	M	M
3	_		_		_	_		_		BM
2	M	_	M	M	M	M	_	EBM	—	M
1			M			M				M
	220	221	222	223	224	225	226	227	228	229
12	EBM	$\mathbf{E}\mathbf{M}$	EM	EM	EMB	_	EMB	EBM		_
11	EBM	_		M	M	_	BM	M	_	_
10	\mathbf{EBM}	M	M	M	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	EBM	EBM	M	
9	EBM		_			-	M	M	В	В
8	EBM	EBM	EBM	EBM	EBM	EBM	EBM	EBM	EBM	M
7	EBM	_	В	В	В			В	В	В
6	\mathbf{EBM}	EMB	EMB	EMB	$\mathbf{E}\mathbf{M}\mathbf{B}$	EMB	EMB	EBM	EMB	EMB
5	EBM				-	_	M	M	В	В
4	EBM	M	M	M	EBM	M	EBM	EBM	M	M
3	\mathbf{EBM}			M	M	_	$\mathbf{B}\mathbf{M}$	M	В	
2	$\mathbf{E}\mathbf{B}\mathbf{M}$	\mathbf{M}	M	M	EBM	_	EBM	EBM	M	_
1	EBM		M	M	M	_	BM	M	_	
	230	231	232	233	234	235	236	237	238	239
12	M	M	_	_	EBM	$\mathbf{E}\mathbf{M}$	$\mathbf{E}\mathbf{M}$		_	EMB
11	M	M	_	_	EBM	M	_		EMB	_
10	EBM	EBM	M	M	EBM	M	M	M	_	EBM
9	В	M		_	EBM	M	В	_	EMB	
8	$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM	M	EBM	EMB	EBM	EBM	EBM	_	EBM
7	В	В	_	В	_	\mathbf{M}	В	_	BM	В
6	EBM	EBM	EMB	EBM	EMB	\mathbf{EMB}	\mathbf{B}	EBM	EBM	EMB
5	В	В		В		M	BM		BM	_
4	EBM	EBM	M	M	EBM	EBM	M	M		EBM
3	_	M		_	EBM	M	_		EMB	
2	M	M	M		EBM	M	M			EBM
1	M	<u>M</u>	<u> </u>	_	EBM	M	M	_	EMB	M
M — Make B — Break		See Re	qt 2.11		ВМ —	Break Make	, marking			
D Dieak			-			Early Make	-		See Re	qt 2.11
						Early Break	Make		and 2.1	_
						Early Make				

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING CO	MBINATION	FIGURE NU	VIBERS			
	240	241	242	243	244	245	246	247	248	249
12	_	M	_	EM	$\mathbf{E}\mathbf{M}$		_	M	EM	EBM
11		M		M	M	-	_	M	_	EBM
10	EBM	EBM		M	M	EBM	_	M	M	EBM
9	_	M			M	В	_		_	EBM
8	EMB	EBM	M	EBM	EBM	EBM	EBM	EBM	M	EMB
7	_		В	В	В	В	В	В	В	EBM
6	EMB	EBM	EBM	EMB	EMB	$\mathbf{E}\mathbf{B}\mathbf{M}$	$\mathbf{E}\mathbf{B}\mathbf{M}$	\mathbf{EBM}	EMB	EMB
5	EM	M	В		В	В	В		В	EMB
4	EB	EBM	M	EBM	M	EBM	M	EBM	M	EBM
3	_	M	_		M	В	_	M		EBM
2	_	M		M	M	M		M	M	EBM
1		M		M	M			M		EBM
	250	251	252	253	254	255	256	257	258	259
12	$\mathbf{E}\mathbf{M}$	_	EMB		EBM	EM		$\mathbf{E}\mathbf{M}$	—	EBM
11	В	_	M		EBM	M	,—	M		\mathbf{EBM}
10	EBM	_	EBM	M	EBM	M	M	\mathbf{EBM}	_	EBM
9	В	_	M			_	В	M		EBM
8	EBM	EBM	EBM	EBM	EMB	M	EBM	EBM	EMB	$\mathbf{E}\mathbf{M}$
· 7	В	В	_			В	В	_	_	_
6	EMB	EMB	EMB	\mathbf{EMB}	EMB	$\mathbf{E}\mathbf{M}$	EMB	EMB	EMB	EME
5	В	В				В	В	M		EM
4	EBM	_	$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM	\mathbf{EBM}	\mathbf{M}	$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM	M	EBM
3	В	_	M			M	В	M		EBM
2	M	$\overline{}$	EBM		EBM	M	_	EBM		EBM
1	M	_	M		EBM	M		M		EBM
	260	261	262	263	264	265	266	267	268	269
1.2		M	M	M		$\mathbf{E}\mathbf{M}$	EM	_	M	M
11		M	M	M	_	В	M	_	M	_
10	_	M	EBM	\mathbf{EBM}	M	EBM	M	M	M	M
9	EB	_	M		В	В	В		M	
8	\mathbf{EMB}	EBM	EMB	EBM	EBM	EBM	M	EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	EME
7	EB	В		В	В	В	В	-		—— ——
6	EMB	EBM	EMB	EBM	EBM	EMB	EM	$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM	EME
5	В	В			В	В	В			EM
4	M	M	EBM	EBM	M	EBM	M	EBM	EBM	_
3		M	M	7.6		В			M	 _
2		M	EBM	M		EBM	M		M	M
1		M	M	M			M		M	
M — Make B — Break		See Re	eqt 2.11	•	EM-	Early Brea Early Mak	e i		See Re	
					EBM-	Early Brea	k Make		and 2 .	12.

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

	CONTACT 'POSITIONS			;	SPRING CON	BINATION	FIGURE NUM	IBERS			
		270	271	272	273	274	275	276	277	278	279
	12	EM	EMB	В	_	_	EBM	EMB	EM	EB	EMB
	11	M	M	_			EBM		В	EBM	— EMD
	10	M	EBM	EBM	EBM	M	EBM	EBM	M	EBM	M
	9	M	_	_	В	_	EB	— —	В	EBM	B
	8	EBM	EBM	EBM	EBM	EBM		EBM	EBM	В	M
	7	В	В	_	В	_	M	_	В	M	В
	6	EMB	EMB	EMB	EBM	В	\mathbf{EMB}	EMB	EMB	В	EMB
_	5	M	_	-	В				В	EMB	В
	4	EBM	EBM	EBM	EBM	M	EBM	M	M	M	M
	3	M		_	\mathbf{B}	_	$\mathbf{E}\mathbf{B}$	В	В	EBM	
	2	M	\mathbf{EBM}	_	_	EBM	\mathbf{EBM}	\mathbf{EBM}	M	$\mathbf{E}\mathbf{B}\mathbf{M}$	_
_	1	M	M				EBM	В	BM	EBM	
		280	281	282	283	284	285	286	287	288	289
	12	M	$\mathbf{E}\mathbf{M}$	_	M	_	M	M			M
	11	_	M		M	_	M	_		_	M
	10	M	M	M	M	M	M	$\mathbf{E}\mathbf{B}\mathbf{M}$	\mathbf{M}	M	M
_	9		BM		BM		В	_	_		
	8	$\mathbf{E}\mathbf{B}\mathbf{M}$		EMB	EBM	В	EBM	В	EMB	EBM	EM
	7	В	BM		BM	_	В		_	_	M
	6	$\mathbf{E}\mathbf{B}\mathbf{M}$		EMB	\mathbf{EBM}	В	\mathbf{EBM}	В	EMB	EMB	$\mathbf{E}\mathbf{M}$
_	5	В	BM		BM		В		EM		EM
	4	EBM	M	M	EBM	EBM	M	EBM	_	M	
	3		BM	_	M	_	M	_	_	_	M
	2	M	M	M	M	M	M	\mathbf{M}	M	M	M
	1				M		M				<u>M</u>
		290	291	292	293	294	295	296	297	298	299
	12	EMB	В	_	_	_		_		M	EBM
	11	 ED	M		_	3_	_	_	_	M	EMB
	10	EB	EBM	_	_	M	M	M	M	EBM	EBM
	9				B			В			EMB
	8 7	EB	EBM	EBM	EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	M	EMB	EBM	EBM
	6	EMD	EMD	B	В	-	В	B	EB	M	BM
	5	EMB —	EMB	EMB B	EBM B	EBM —	EMB B	EMB B	EMB —	EBM M	EBM BM
	4	EBM		M	M	M					
	3		В		В		M —	M	EBM	EBM	EBM
	$\overset{\circ}{2}$		EBM	_	_	M	M			M	EMB
	1		BM	_	_	—		_		M M	EBM EMB
	M — Make	-·	O - P	1011		ВМ —	Break Make	?		 .	
	B-Break		see Ke	m qt~2.11			Early Break			~ -	
							Early Make				qt 2.11
							Early Break			and 2.1	12.
							Early Make				

SECTION 040-930-701

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING CO	OMBINATION	I FIGURE NU	MBERS			
	300	301	302	303	304	305	306	307	308	309
12	_		EM		EM	EM	EM	M	EM	EM
11	_	_		_	BM	_	M	M	В	
10	M	$\mathbf{E}\mathbf{B}\mathbf{M}$		M	M	M	EBM	EBM	M	M
9	_	M	BM		В	В	В	_	$\mathbf{B}\mathbf{M}$	В
8	EBM	EBM	_	EMB	M	EBM	EBM	EBM		EBM
7		M	BM		В	В	B	_	В	В
6	EBM	\mathbf{EBM}	_	EMB	$\mathbf{E}\mathbf{M}$	EMB	EMB	EBM	_	В
5		M	BM		В	В	В	_	В	BM
4	$\mathbf{E}\mathbf{B}\mathbf{M}$	\mathbf{EBM}	_	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	EBM	EBM	EBM	M	EBM
3	_	M	_		В		В	_	$\mathbf{B}\mathbf{M}$	_
2	M	\mathbf{M}	· —	M	M	M	M	\mathbf{EBM}	M	M
1					M	M	M	M	M	M
	310	311	312	313	314	315	316	317	318	319
12	$\mathbf{E}\mathbf{M}$	EBM	EM	M	EBM		EBM	_	_	
11		EBM		M	BM	_	M	_	EMB	M
10	M	EBM	M	\mathbf{EBM}	EBM	_	EBM	M		M
9	В		_	$\mathbf{E}\mathbf{B}$	M	В	M	В	EMB	
8	EB	В	EBM	EMB	EBM	_	EMB	EBM	EBM	EBM
7	В	_	В	$\mathbf{E}\mathbf{B}$	_	В	EB	В	BM	_
6	В	EMB	EMB	EMB	EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	EMB	EBM	EBM	EMB
5	В	_		В	_	В		В	BM	_
4	M	M	EBM	EBM	M	_	EBM	M	_	M
3	В	$\mathbf{E}\mathbf{B}$	_	$\mathbf{E}\mathbf{B}$	BM	_	M	В	EMB	_
2	M	EBM	M	M	EBM	_	EBM	M		M
1		EBM		M	BM		M	В	EMB	M
	320	321	322	323	324	325	326	327	328	329
12	$\mathbf{E}\mathbf{M}$	M	\mathbf{M}	EBM	_		EBM	$\mathbf{E}\mathbf{M}$	_	_
11	BM	M	EMB	M	_	_	BM	_	_	M
10	\mathbf{M}	\mathbf{M}		EBM	EBM	EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	EBM	M
9	В		В				M	_	M	_
8	EBM	EBM	_		EBM	M	EBM	M	EBM	M
7	В	В	В	M	_	_	M	_	M	В
6	EM	EBM	EB	EMB	EMB	$\mathbf{E}\mathbf{M}$	EBM	EMB	EMB	EMB
5	В	В	В				M		M	В
4	EBM	M	_	M	EBM	M	EBM	M	EBM	M
3	M	В	В			_	\mathbf{BM}	_	M	_
2	EBM	M	M	EBM	EBM	\mathbf{EBM}	\mathbf{EBM}	M	EBM	_
1	M	M	EMB	M		_	BM	M		M
M — Make		Sec Pr	eqt 2.11		BM —	Break Mak	e			
$\mathrm{B}-\mathrm{Break}$		Dec IV	-qι Δ.11	•	EB-	Early Brea	k		Coc D -	~+ 0 11
4.					EM -	Early Make	е			qt 2.11
						Early Brea			and 2.	14.
					EMB —	Early Make	e Break			

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS				SPRING CO	MBINATION	IS FIGURE N	JMBERS			
	330	331	332	333	334	335	336	337	338	339
12	EMB	M	M	M	_	_	EBM	EMB	M	EMB
11	M		M	EM	M		EMB	_	M	
10	EBM	\mathbf{M}	M	M	M	EBM	EBM	M	M	M
9	M		$\mathbf{E}\mathbf{B}$	$\mathbf{E}\mathbf{M}$	M		EMB	_	BM	
8	EBM	EBM	EMB	M	В	EBM	EBM	EBM	EBM	_
7	M	$\mathbf{E}\mathbf{B}$	$\mathbf{E}\mathbf{B}$	$\mathbf{E}\mathbf{M}$	EBM		EMB	_	В	_
6	EM	EBM	EMB	M	В	EBM	EBM	EMB	_	
5	M	EB	В	EM	EMB		EMB	В	BM	В
4	EBM	_	EBM	M	EBM	EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	M	EBM	_
3	M	M	EBM	EM	M	-	\mathbf{EMB}	_	M	\mathbf{BM}
2	M	M	M	M	M	M	EBM	EBM	M	M
1	M	M	M	EM	M		EMB			M
	340	341	342	343	344	345	346	347		
12				EBM		M	$\mathbf{E}\mathbf{B}\mathbf{M}$	$\mathbf{E}\mathbf{M}$		
11				M		_	EMB	_		
10				\mathbf{EBM}		M	EBM	_		
9				M		_	EMB			
8				EBM		EBM	EBM	M		
7				M		_	В	_		
6				EBM		M	EBM	EMB		
5				M		В	BM	В		
4				EBM		M	EBM	_		
3				M		_	EMB	В		
2				EBM M		M	EBM	M —		
-							EMB			
4.0	348	349	350	351	352					
12		M	M		M					
11	**	EMB	M	***						
10 9	M	EBM EM	M M		EBM					
	7.5			#345.7.¢						
8 7	M	M	EBM	EBM	EMB					
6	B EM	B EBM	M	B	EB					
5		В	EBM M	EM	EMB B					
4	M	M		EBM						
3	1VI	EMB	EBM M	E-DIVI	EBM					
2		M	M		M					
1		EMB	M		193					
M — Make		_			RM —	Break Mak	P			
B — Break		See Re	eqt 2.11			Early Brea				
				•		Early Make				qt 2.11
						Early Brea			and 2.	12.
						Early Make				
						-				

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

CONTACT POSITIONS			5	SPRING COM	BINATIONS	FIGURE NUM	/BERS			
	400	401	402	403	404	405	406	407	408	409
12				$\mathbf{E}\mathbf{M}$			EM	PBEM	_	
11	_	_	_	_		_	_	_		_
10	M	EBM	EBM	\mathbf{EBM}		EBM	$\mathbf{E}\mathbf{B}\mathbf{M}$	_	EBM	M
9		PM	_	_		_			PMEB	
8	EMB	_		EMB			EMB	EMB	EMB	EMB
7	В	— EDM		В			В	— DDM	BM	В
6 5	EBM B	EBM —	EBM 	EBM B		_	EBM B	EBM BM	EBM BM	EBM B
										
$rac{4}{3}$	PM —	PM M	PM 	PM 			PM B	— В	PMEB BM	РМ В
$\frac{3}{2}$			_	EM		PBEM	EM	EM	EM	_
1			_			- DEM	-	В	_	_
	410	411	412	413	414	415	416	417	418	419
12	PB	_	PBEM	EM	PBEM	PBEM		PB	$\mathbf{E}\mathbf{M}$	_
11	M	$\mathbf{B}\mathbf{M}$	_	$\mathbf{B}\mathbf{M}$	BM	0	M	M	BM	M
10	M	$\mathbf{E}\mathbf{B}\mathbf{M}$		M	EBM	EBM	EBM	$\mathbf{E}\mathbf{B}$	$\mathbf{E}\mathbf{B}\mathbf{M}$	EBM
9	_			PMEB	PMEB	_		PM		
8	EMB	$\mathbf{E}\mathbf{M}$	EMB	EMB	EMB	EMB	EMB		$\mathbf{E}\mathbf{M}$	EMB
7	— EDM	В	_	В	BM	— ED14	В	M		В
6 5	EBM B	EBM B		M B	EBM BM	EBM —	EBM B	EBM M	EBM —	EBM B
$\frac{4}{3}$		PM B	_	PMEB M	PMEB BM	— BM	PM —	— М	PM BM	PMEB —
$\overset{3}{2}$	PBEM		PBEM	PBEM	PBEM	PBEM	EM	PB	EM	PBEM
1	M	BM	_	M	BM	BM	M	M	M	M
	420	421	422	423	424	425	426	427		
12	EM		$\mathbf{E}\mathbf{M}$	PB		EMPB	EBM	EM		
11	В		В	M	BM	_	EBM	M.		
10	M	M	\mathbf{M}	$\mathbf{E}\mathbf{B}$	EBM	EBM	EBM	M		
9		_	PMEB	PM			EBM			
8	$\mathbf{E}\mathbf{M}$	EMB	$\mathbf{E}\mathbf{M}$	EM	EMB	EMB	EMB	EM		
7	В	В	В	M	В		PMEB	353533333333333333333		
6 5	EBM B	EBM B	EBM B	EBM M	EBM B	EBM M	EMB EMB	EBM		
										
$rac{4}{3}$	PM B	PM B	PM B	<u></u>	PMEB	— В	EBM EBM	PM M		
$\frac{3}{2}$	EM	EM	EM	PB	PBEM	D	EBM	EM		
1	В		В	M	M	M	EBM	M		
M — Make B — Break	•	See Re	qt 2.11.		EBM -	Preliminar Early Brea Early Make	k Make			
BM — Break Ma EB — Early Bro EM — Early Ma PM — Prelimina	eak ke	e	See Reand 2.1	qt 2.11 .2.	PBEM —	Preliminar Early Make Preliminar Early Breal	y Break e y Make		See Reand 2.1	

TABLE A - SPRING COMBINATION FIGURE NUMBERS AND CONTACT POSITIONS (Cont)

					
CONTACT		SPRING COM			
POSITIONS	FIGURE NUMBER				
		500	501		
12 & 24		M	В		
11 & 23		\mathbf{M}	В		1
10 & 22		M	В		
 9 & 21		${f M}$	В		
8 & 20		M	В		
7 & 19		M	В		
6 & 18		M	В		
5 & 17		M	В		
4 & 16		M	В	,	
3 & 15		M	В		
$2 \;\&\; 14$		M	В		
1 & 13		M	B		

M — Make See Reqt 2.11.